HISTORIC RESOURCE INVENTORY FORM Resource Address: 1226 Amarillo St Abilene Texas 79602 United States County: Taylor Historic name: Jones/Holly House Present name: Jones/Holly House Local place name: Visible from public right of way: Yes Ownership: Private Owner/Address: Land unit size: Site/Setting: **Historical Information** Historic Function: Domestic: Single Dwelling Construction Date: ca. 1920-1929, 1920* Original or Significant Owners: Significant Date/Period: Areas of Significance: **Architectural Information** Category: building, domestic building Structural: balloon frame Е



Current Function: Domestic: Single Dwelling Architect: Builder: Developer:

Style: Craftsman	Additions
Exterior Material(s): original brick, original wood siding	Alterations
Roof Material: replacement asphalt shingles	☐ Moved ☐ Other
Roof Type: Cross gable, box cornice	Ancillary structure
Vindows: replacement aluminum 1/1 double-hung sashes	

Porch: single-story two-bay open porch

Chimney(s):

Status (Current Listing or Designation)				
National:	$\hfill \square$ indiv. $\hfill \square$ district $\hfill \square$ landmrk.			
State/Province:	$\hfill \Box$ indiv. $\hfill \Box$ district $\hfill \Box$ landmrk.			
Local:	${\color{red} \checkmark}$ indiv. ${\color{gray} \bigcirc}$ district ${\color{gray} \bigcirc}$ landmrk.			

Stories: 1, Bays: 3

Foundation: undetermined General condition: Good

Basement: undetermined

Historical Summary:

Form or Plan: bungalow, rectangular

Evaluation (Preparer's Assessment of Eligibility)				
Recommendation	Level of potential eligibility	Landmark potential		
Individually eligible	National	National		
Eligible as contributing resource	State	State		
Not eligible / non-contributing	Local	Local		
Not determined				



1996



1996

Description/Remarks

This is a 1-story, 3-bay domestic building in the Craftsman style built in 1920. The structural system is balloon frame. The foundation is undetermined. Exterior walls are original brick and original wood siding. The building has a cross gable roof clad in replacement asphalt shingles with box cornice. Windows are replacement aluminum, 1/1 double-hung sashes. There is a single-story, two-bay open porch characterized by a gabled roof clad in asphalt shingles with square brick posts.

Date source: Taylor CAD

Survey and Recorder		
Project: City of Abilene - Historic Buildings and Districts	Sequence/Key no.: 19	Survey Date: 10/20/11
Prepared By: Abrigg	Report Title/Name: Texas SHPO Grant to update existing Survey	Previous Surveys:
Inventoried: 10/15/2012 10:13:49 am Last updated: 01/04/2017 10:15:29 am by Hayden Brodowsky /	Level of Survey: ✓ Reconnaissance Intensive	Additional Research Recommended? ✓ Yes No