

# HISTORIC RESOURCE INVENTORY FORM

Resource no.

Resource Address:

**818 Cedar St  
Abilene Texas 79601 United States**

County: Taylor

Historic name: Copper/Jimenez House

Present name: Copper/Jimenez House

Local place name:

Visible from public right of way: Yes

Ownership:

Owner/Address:

/

Land unit size:

Site/Setting:



Lat/Long: 32.4580068415107700, -99.7349388048934900 [WGS84]

UTM: Zone 14S, 430927.5859 mE, 3591441.8929 mN

Parcel No.

## Historical Information

Historic Function: Domestic: Single Dwelling

Construction Date: ca. 1920-1929 , 1925\*

Original or Significant Owners:

Significant Date/Period:

Areas of Significance:

Current Function: Domestic: Single Dwelling

Architect:

Builder:

Developer:

## Architectural Information

Category: building, domestic building

Structural: undetermined

Stories: 1.5, Bays: 3

Form or Plan: bungalow, rectangular

Foundation: undetermined

General condition: Good

Basement: undetermined

Style: Eastlake/Folk Victorian and Late Victorian

Exterior Material(s): original wood siding

Roof Material: replacement asphalt shingles

Roof Type: Hipped gable

Windows: 1/1 double-hung sashes

Chimney(s):

Porch: full-span enclosed porch

Additions

Alterations

Moved

Other

Ancillary structures:

## Historical Summary:

## Status (Current Listing or Designation)

National:  indiv.  district  landmrk.

State/Province:  indiv.  district  landmrk.

Local:  indiv.  district  landmrk.

## Evaluation (Preparer's Assessment of Eligibility)

### Recommendation

- Individually eligible  
 Eligible as contributing resource  
 Not eligible / non-contributing  
 Not determined

### Level of potential eligibility

- National  
 State  
 Local

### Landmark potential

- National  
 State  
 Local



**Description/Remarks**

This is a 1.5-story, 3-bay domestic building in the Eastlake/Folk Victorian style with Late Victorian influences built in 1925. The structural system is undetermined. The foundation is undetermined. Exterior walls are original wood siding. The building has a hipped gable roof clad in replacement asphalt shingles. Windows are , 1/1 double-hung sashes. There is a full-span enclosed porch characterized by a hip-and-gable roof clad in asphalt shingles with arcaded arch posts.

-----  
Date source: Taylor CAD

**Survey and Recorder**

Project: City of Abilene - Historic Buildings and Districts	Sequence/Key no.: 50	Survey Date: 10/2011
Prepared By: Hill	Report Title/Name: Texas SHPO Grant to update existing Survey	Previous Surveys:
Inventoried: 10/22/2012 9:38:03 am Last updated: 01/06/2017 10:00:14 am by Hayden Brodowsky /	Level of Survey: <input checked="" type="checkbox"/> Reconnaissance <input type="checkbox"/> Intensive	Additional Research Recommended? <input type="checkbox"/> Yes <input type="checkbox"/> No