

HISTORIC RESOURCE INVENTORY FORM

Resource no.

Resource Address:
710 Meander St
Abilene Texas 79601 United States

County: Taylor

Historic name: Clark/Boyce House

Present name: Clark/Boyce House

Local place name:

Visible from public right of way: Yes

Ownership: Private

Owner/Address:

/

Land unit size:

Site/Setting:



Lat/Long: 32.442498000000000, -99.7458189999999800 [WGS84]

UTM: Zone 14S, 429892.9897 mE, 3589729.7620 mN

Parcel No.

Historical Information

Historic Function: Domestic: Single Dwelling

Construction Date: ca. 1920-1929 , 1927*

Original or Significant Owners:

Significant Date/Period:

Areas of Significance:

Current Function: Domestic: Single Dwelling

Architect:

Builder:

Developer:

Architectural Information

Category: building, domestic building

Structural: frame

Stories: 1, Bays: 1

Form or Plan: bungalow, rectangular

Foundation: undetermined

General condition: Excellent

Basement:

Style: Craftsman

Exterior Material(s): original wood siding

Roof Material: replacement asphalt shingles

Roof Type: Medium front gable , open cornice , gable brackets

Windows: replacement double-hung sashes

Chimney(s):

Porch: single-story full-span open porch

Additions

Alterations

Moved

Other

Ancillary structures:

Historical Summary:

Status (Current Listing or Designation)

National: indiv. district landmrk.

State/Province: indiv. district landmrk.

Local: indiv. district landmrk.

Sayles Boulevard District

Evaluation (Preparer's Assessment of Eligibility)

Recommendation

- Individually eligible
 Eligible as contributing resource
 Not eligible / non-contributing
 Not determined

Level of potential eligibility

- National
 State
 Local

Landmark potential

- National
 State
 Local



1996

Description/Remarks

This is a 1-story, 1-bay domestic building in the Craftsman style built in 1927. The structural system is frame. The foundation is undetermined. Exterior walls are original wood siding. The building has a medium front gable roof clad in replacement asphalt shingles with open cornice , gable brackets. Windows are replacement double-hung sashes. There is a single-story, full-span open porch characterized by a gabled roof clad in asphalt shingles with square wood posts on square brick piers.

Date source: Taylor CAD

Survey and Recorder

Project: City of Abilene - Historic Buildings and Districts	Sequence/Key no.: 220	Survey Date: 11/2011
Prepared By: Abrigg	Report Title/Name: Texas SHPO Grant to update existing Survey	Previous Surveys:
Inventoried: 10/22/2012 12:40:57 pm Last updated: 04/11/2017 9:15:46 am by Hayden Brodowsky /	Level of Survey: <input checked="" type="checkbox"/> Reconnaissance <input type="checkbox"/> Intensive	Additional Research Recommended? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No