# HISTORIC RESOURCE INVENTORY FORM

Resource Address: **224 Merchant St Abilene Texas 79601 United States** County: Taylor Historic name: Chambers House Present name: Chambers House Local place name: Visible from public right of way: Yes Ownership: Private Owner/Address: / Land unit size:

Site/Setting:

### **Historical Information**

Historic Function: Domestic: Single Dwelling Construction Date: ca. 1910-1919, 1910\* Original or Significant Owners: Significant Date/Period: Areas of Significance:

## **Architectural Information**

Category: building, domestic building Structural: frame Stories: 1, Bays: 3 Form or Plan: rectangular Foundation: undetermined General condition: Basement: none

**Historical Summary:** 

Lat/Long: 32.4520198931363800, -99.7436946736106600 [WGS84] UTM: Zone 14S, 430100.0325 mE, 3590783.9123 mN Parcel No.

Current Function: Vacant/Not in Use Architect: Builder: Developer:

Style: Folk/Traditional and Craftsman Exterior Material(s): original wood siding Roof Material: replacement asphalt shingles Roof Type: Pyramidal , raked box cornice Windows: original wood 1/1 double-hung sashes Chimney(s): Porch: single-story two-bay open porch

#### Demolished: 2013

- Additions Alterations
- Moved
- Other
- Ancillary structures:

**Status** (Current Listing or Designation)

National:	$\hfill \square$ indiv. $\hfill \square$	district $\Box$	landmrk.
State/Province:	$\hfill \square$ indiv. $\hfill \square$	district 🗌	landmrk.
Local:	$\hfill \square$ indiv. $\hfill \square$	district 🗌	landmrk.

Evaluation	(Preparer's	Assessment	of E	Eligibility	)
------------	-------------	------------	------	-------------	---

Recommendation
Individually eligible
Eligible as contributing resource
Not eligible / non-contributing
Not determined

0	·,))
Lev	el of potential eligibility
	National
	State
$\square$	Local



1997



April 2013



April 2013

## **Description/Remarks**

This is a 1-story, 3-bay domestic building in the Folk/Traditional style with Craftsman influences built in 1910. The structural system is frame. The foundation is undetermined. Exterior walls are original wood siding. The building has a pyramidal roof clad in replacement asphalt shingles with raked box cornice and one gabled dormer. Windows are original wood, 1/1 double-hung sashes. There is a single-story, two-bay open porch characterized by an integrated (under the main) roof clad in asphalt shingles with square wood posts. After a devastating fire in April 2013, this structure cannot be rehabilitated. It was demolished and removed from property.

Date source: Taylor CAD

Survey and Recorder		
Project: City of Abilene - Historic Buildings and Districts	Sequence/Key no.: 226	Survey Date: 2/2012
Prepared By: Abrigg	Report Title/Name: Texas SHPO Grant to update existing Survey	Previous Surveys:
Inventoried: 10/22/2012 12:43:56 pm Last updated: 03/01/2017 5:19:35 pm by Hayden Brodowsky /	Level of Survey: ✓ Reconnaissance ☐ Intensive	Additional Research Recommended? ✓ Yes □ No

Inventory Sheet : Chambers House : 224 Merchant St Abilene Taylor Texas