HISTORIC RESOURCE INVENTORY FORM

Resource Address: **1918 S 6th St Abilene Texas 79601 United States** County: Taylor Historic name: Leach/Dodd House Present name: Leach/Dodd House Local place name: Visible from public right of way: Yes Ownership: Private Owner/Address: /

Land unit size: Site/Setting:

Historical Information

Historic Function: Domestic: Single Dwelling Construction Date: ca. 1930-1939, 1930* Original or Significant Owners: Significant Date/Period: Areas of Significance:

Architectural Information

Category: building, domestic building Structural: frame Stories: 1, Bays: 2 Form or Plan: bungalow, rectangular Foundation: undetermined General condition: Excellent Basement: undetermined

Historical Summary:



Lat/Long: 32.444533000000000, -99.7460467478851400 [WGS84] UTM: Zone 14S, 429873.1567 mE, 3589955.5000 mN Parcel No.

Current Function: Domestic: Single Dwelling Architect: Builder: Developer:

Style: Craftsman Exterior Material(s): original brick, original wood siding Roof Material: replacement asphalt shingles Roof Type: Multi-plane front gable , box cornice Windows: original wood vertical 4/1 double-hung sashes Chimney(s): one brick side right exterior Porch: single-story corner wrap-around open porch

\Box	Additions (1940's
	Alterations

- Moved
- Other
- Ancillary structures:

Status (Current Listing or Designation)

National:	indiv. district landmrk.
State/Province:	indiv. district landmrk.
Local:	\checkmark indiv. \square district \square landmrk.

、 1
Recommendation
Individually eligible
Eligible as contributing resource
Not eligible / non-contributing
Not determined

igiointy)
Level of potential eligibility
National
State
Local

Landmark potential
National
State
Local

Resource no.



1997



Description/Remarks

This is a 1-story, 2-bay domestic building in the Craftsman style built in 1930. The structural system is frame. The foundation is undetermined. Exterior walls are original brick and original wood siding. The building has a multi-plane front gable roof clad in replacement asphalt shingles with box cornice. There is one side right, exterior, brick chimney. Windows are original wood, vertical 4/1 double-hung sashes. There is a single-story, corner wrap-around open porch characterized by a gabled roof clad in asphalt shingles with square brick posts.

Date source: Taylor CAD

Survey and Recorder

Project: City of Abilene - Historic Buildings and Districts Prepared By: Abrigg

Inventoried: 10/22/2012 2:20:05 pm Last updated: 01/03/2017 11:28:55 am by Hayden Brodowsky / Sequence/Key no.: 370

Report Title/Name: Texas SHPO Grant to update existing Survey Level of Survey: Reconnaissance Intensive Survey Date: 12/2011 Previous Surveys:

Additional Research Recommended?

Inventory Sheet : Leach/Dodd House : 1918 S 6th St Abilene Taylor Texas